					- 1720 N SEDGWICK ST
•	Address	Арр.Туре	Insp.Type	Viol. Date	Violation Desription
1720 N SEDG	VICK ST	CN_COMPL	CN_COMPL	01/27/2009	CN104035: MAINTAIN WINDOW
Failed to maint	ain windows in sound	condition and go	ood repair. (13-19	6-550(b) and (f)	
North rotted wi					
1720 N SEDG\		_	CN_COMPL		CN104025: MAINTAIN WINDOW SASH
		ood condition and	d so it fits reasona	bly tight within it	ts frame. (13-196-550(b))
North rotted wi					
1720 N SEDG			CN_COMPL		CN067024: REPAIR EAVES
					ay admit rain. (13-196-530, 13-196-530(c), and 13-196-641)
	ion of eaves falling a				
1720 N SEDG			CN_COMPL		CN061014: REPAIR EXTERIOR WALL
				holes, breaks, l	oose or rotting boards or timbers and any other conditions which might admit rain o
	ne walls. (13-196-530	D(D), 13-196-641)			
	h, front rotted siding.			01/07/0000	CN077014: REPAIR FENCE
1720 N SEDG		_	CN_COMPL		
Front rotted 6'	ain fence in good con	iuition and repair.	. (7-28-060, 13-18	96-630, 13-196-	041)
1720 N SEDG			CN COMPL	01/27/2009	CN076034: REPAIR GUTTER
		_			196-630(b), 13-196-641, 18-29-1101, 18-29-1105, 18-29-1106)
	ner falling gutter.	o repair and wor	King condition. (1	5-150-550, 15-1	190-030(b), 13-190-041, 10-23-1101, 10-23-1103, 10-23-1100)
1720 N SEDG	00	CN COMPL	CN COMPL	01/27/2009	CN068014: REPAIR ROOF STRUCTURE
		_			ects which may admit rain. (13-196-530, 13-196-530(e), 13-196-641)
	ion of roof broken an				
1720 N SEDG			CN COMPL		CN070034: REPLACE D&H PORCH
	d or replace dilapidate				
					nandrails, missing pickets, handrails under 42", rotted stair stringers, rotted stair
treads, missing	stair risers, over not	ched columns, co	olumns to beams r		pen fire cuts, 6x6 beams at 8' span, lower handy man deck falling and collapsing.
	nits required for rear			-	
1720 N SEDG			CN_COMPL		CN138056: DEBRIS, EXCESSIVE
	nulation of refuse and			(13-196-580, 13	-196-630)
Rear at 2nd flo	or back and at grade	junk wood debri	s nlywood		

Rear at 2nd floor back and at grade junk, wood debris, plywood.



Case. No.201748Case Entered Date: 03/11/2009Address:1720 N. SEDGWICK STCase. Type:CONSERVATION COMPLAINT INVST(Description:311 complaint SR# 802415869

Case Status: Open

				Insp	pections			
Insp. #	Insp. Type	Partial	Waived	Started	Completed	Insp. By	Status	Modified By
2670378	CN_COMP	L N	Ν	01/27/2009	01/27/2009	BL01037	FAILED	BL07004
from def	ects which m	ay admit	rain. (13-	196-530, 13-	l condition and 196-530(e), 13 d and buckled	8-196-641) So		OPEN
which m		. (13-196	6-530, 13- ⁻	196-530(c), a	air and free frond nd 13-196-641			OPEN
(13-196-		630(b), 1	3-196-641		pair and worki , 18-29-1105,			OPEN
breaks, l	oose or rottin	ig boards	or timber	s and any oth	building or struter conditions with the conditions with the conditions with and structure struct	which might ad	dmit rain	OPEN
	35 - Failed to 550(b) and (f				dition and goo	d repair.		OPEN
					condition and s ndow sashes.	so it fits reasor	nably	OPEN
					ris and keep p at grade junk,			OPEN
	14 - Failed to 641) Front rot			good conditio	n and repair.	(7-28-060, 13-	196-630,	OPEN
13-196-6 missing treads, r	641) Rear 2 s handrails, mis nissing stair r	tory, woo ssing picl isers, ove	d porch is kets, hand er notched	dangerous a rails under 42 columns, co	nd dangerous and hazardous 2", rotted stair lumns to bean k falling and co	It has rotted of stringers, rotted of stringers, rotted of stringers, rotted of string bol	decking, ed stair Its, open	OPEN

permits required for rear porch replacement.

CIT OF CHICAED		172	0 N. SEDO	GWIC	K ST			CA: 07
	App. Type: PERM	IIT - ELECTRIC \	WIRING			Estima	ted Cost:	\$1,200.00
PROVIDED AND MARK	App. No. 10063	8645 App. Date	: 03/09/2016	6	Status: Pr	e-Issued	(Fee Calculate	ed)
INSTALL N	EW LIGHTS, SWI	TCHES AND	OUTLETS	. NEW	/ A/C UNIT	Γ.		
Inspector:		BL No	Ins	pection	Date:/_	/	nsp. No	
Inspection Res	sult Passed 🗌 F	ailed Final] Partial]	No Entry] Void P	ermit 🗌 Sto	p Order 🗌
		Build	ling Informa	tion				
No. Stories	0 Constr Type		re Escape	N	Exempt	N	Lot Width	0
Width Length	0 Attic 0 Basement		Detector	Ν	Annual CN Fee	N 80	Lot Length Lot Area	0
Area	0 Height		Porch			00	LULAICA	
Dwelling Unit	ts: Attic 0 Room	ning 0 Non-Res	sid 0 Base	ment	0 Family	0 Origin	al 0 Total U	nits 0
		Applicant	t /Owner Info	ormatic	on			
	CRISAN DANIEL 3 N. MAPLEWOOD A	VE. CHICAGO	IL 60645		C Mob		764-9608	
	D.C.L. ELECTRIC 3 N. MAPLEWOOD A	VE. CHICAGO	IL 60645-		D Mob		764-9608 x	
		Contra	actor Inform	ation				
Type: ELE	CT Name: D.C	.L. ELECTRIC			Pł	none: (77	3)764-9608 x	
	N. MAPLEWOOD A							
Lic. No.: EC	C92055 Exp 5451 Exp	oires:01/31/2017 oires:01/31/2017						
	Fee Description		Amoun	t	Waived	Status		
EL PERMIT F	EE - BRANCH CIRC			0.00	Ν	UNPAID		
		Total Fees:	\$30	0.00				

CIT OF CHICAGO			172	DGWIC	K ST	CA: 07			
	App. Type: PERM	IT - EAS	Y PERM	IIT PROCE	ESS		Estima	ted Cost:	\$50,000.00
E A CONTRACTOR OF A CONTRACTOR	App. No. 10060	9227 A p	op. Date	: 08/12/20	15	Status: Fi	nal Data F	Review	
QTY 3, DRYW (REPLACEMI REPLACE CA	REPLACEMENT /ALL REPLACE ENT ONLY): QT ABINETS AND F N-HISTORIC SI	MENT, Y 1, RE LOORI	INTER PLAC NG, R	RIOR DO E ALL P EPLACE	or re Lumb And	EPLACEMI ING FIXTU TEAR OFF	ENT, HO RES SA	OT WATER	HEATER TION,
							/	Insp. No.	
	t Passed E								p Order 🗌
	r		Build	ing Inforn	nation	-1	1		
No. Stories	0 Constr Type			e Escape	N	Exempt		Lot Width	0
Width	0 Attic	N		Detector	N	Annual	N	Lot Length	0
Length Area	0 Basement 0 Height	N	00	Detector Porch		CN Fee	80	Lot Area	0
Dwelling Units:		ing 0 I	Non-Res		sement	0 Family	0 Origin	al 0 Total U	nits 0
		A	oplicant	/Owner Ir	nformati	on			
	OUNES JOSEPH '. WASHINGTON S					I	Day: (312) bile:	802-1122	
	OUNES JOSEPH '. WASHINGTON S	T. SUITE	E 600 CH	HICAGO IL	. 60602		Day: (312) bile:	802-1122	
	OUNES JOSEPH . WASHINGTON S	T. SUITE	E 600 CH	HICAGO IL	. 60602		Day: (312) bile:	802-1122	
	OUNES JOSEPH 7. WASHINGTON S	T. SUITE	E 600 CH	HICAGO IL	. 60602		Day: (312) bile:	802-1122	
	Fee Description			Amou	Int	Waived	Status		
	RAL FEE - RENO/AI	TER			25.00	Ν	UNPAID	_	
DOORS					25.00	Ν	UNPAID	_	
· · · · · · · · · · · · · · · · · · ·	E - WATER HEATE	RS			\$50.00	N	UNPAID	_	
WINDOWS					25.00	N	UNPAID	_	
ZONING FEE -	RENOVATION/ALT				\$50.00	Ν	UNPAID		
		Total	Fees:	\$4	175.00				

1720 N. SEDGWICK ST

App. Type: PERMIT - EASY PERMIT PROCESS

App. No. 100309684 App. Date: 09/09/2009 Permit Issued: 09/09/2009

	REPAIRS TO ROOF AND EAVES. REPAIRS TO WINDOWS SASHES AND FRAMES AS NEEDED NO CHANGES TO EXISTING									
Inspector:			BL N	0	Ir	spectio	n Date:		Insp. No	
		Passed 🗌 F							Permit 🗌 Sto	p Order 🗌
				Buildi	ing Inforn	nation				
No. Stories	0	Constr Type		Fire	e Escape	Ν	Exemp	ot	Lot Width	0
Width	0	Attic	Ν		Detector	Ν	Annua		Lot Length	0
Length	0	Basement		CO	Detector		CN Fe	e 80	Lot Area	0
Area	0	Height			Porch					
Dwelling Ur	nits: A	ttic 0 Room	ning 0	Non-Res		sement		y 0 Origin	al 0 Total U	Inits 0
			A	oplicant	/Owner Ir	nformat	ion			
OWNER		GELIS RICHA							642-0044 x	
Address: 17	20 N SEI	DGWICK CH	ICAGO II	_ 60600			Μ	lobile:		
EMERG	DANIG	GELIS RICHA	RD					Day: (312)	642-0044 x	
Address: ,							Μ	lobile:		
OWNCONT	RDANIG	GELIS RICHA	RD					Day:		
Address: ,							Μ	lobile:		
	Fee	Description			Amou	Int	Waived	Status		
ARCHITEC	TURAL F	EE - RENO/A	LTER		\$1	25.00	Ν	PAID		
ZONING FE	EE - REN	OVATION/ALT	FERATIO	N	9	650.00	Ν	PAID		
			Total	Fees:	\$1	75.00				

CA: 07

\$5,000.00

Estimated Cost:

|--|

STI OF CHICAGE			1720 N. SED	GWICK	(ST			CA: 07		
	App. Type: P	ERMIT - REN	IOVATION/ALTERAT	ION		Estima	ted Cost:	\$65,000.00		
REAL TED ATT THE	App. No. 10	00638741 A	op. Date: 03/14/2010	6 Permi	t Issued: 06	/01/2016				
INTERIOR ALTERATIONS TO AN EXISTING 2 STORY FRAME SINGLE FAMILY RESIDENCE WITH HABITABLE ATTIC SPACE. REFURBISH 1ST STORY STOREFRONT, SAME AS EXISTING. REPLACEMENT OF PORTIONS OF STOREFRONT KNEE WALL THAT ARE BEYOND REPAIR. ALL OTHER ELEMENTS OF FRONT FACADE TO BE REFURBISHED. REPLACEMENT OF 3 STORY OPEN FRAME REAR PORCH WITH NEW PER PLANS. REMOVAL OF EXISTING INTERIOR STAIR, CREATE NEW OPENINGS IN THE FLOOR ON 2ND FL & ATTIC ALONG SOUTH EXT. WALL FOR NEW INTERIOR STAIR. PORTION OF ATTIC FLOOR TO BE OPEN TO BELOW. Inspector:BL No Inspection Date:// Insp. No Inspection Result Passed Failed Final Partial No Entry Void Permit Stop Order										
			Building Informa	ition						
No. Stories	0 Constr T	уре	Fire Escape	Ν	Exempt		Lot Width	0		
Width	0 🗛	ttic N	Smoke Detector	Ν	Annual	Ν	Lot Length	0		
Length	0 Basem 0 He		CO Detector		CN Fee	80	Lot Area	0		
Area Dwelling Units	· · · ·	ight ooming 0	Porch Non-Resid 0 Base	ment	0 Family	Origin	al 0 Total U	nits 0		
		A	pplicant /Owner Inf	ormatio	n					
APPL R0 Address: 3116 \$	OBERT NOLTE S. PRINCETON		CAGO IL 60616		D Mob		404-0529			
-	OUNES JOSEP 1. WASHINGTO		E 600 CHICAGO IL 6	0602	D Mob		802-1122 x			
EMERG YO Address: 2625 Y	OUNES ROSAN W. FARWELL /		GO IL 60645		D Mob		578-1414			
			Contractor Inform	ation						
Type: REFR			NSTRUCTION		Ph	one: (77	3)742-5411 x			
Address:4107 (Lic. No.: 2199		LOOR 1ST S Expires:	KOKIE IL 60076-							
Type: EXPD	Name:	ROBERT NO	OLTER		Ph	one: (31	2)404-0529 X			
Address:3116 S Lic. No.: 2292		AVE. CHICA				X	,			
Type: ELEC	T Name:	D.C.L. ELEC	TRIC		Ph	one: (77	3)764-9608 x			
	N. MAPLEWOO	D AVE. CHI	CAGO IL 60645-			, ,	,			
Lic. No.: ECC	92055	Expires:01/	/31/2017							
Type: ARCH		YANONG AI			Ph	ione:				
Address:9533 \ Lic. No.: 1022		D DES PLAI Expires: 11/	NES IL 60016-1507 30/2016							
Type: GENC		-			Ph	one: (84	7)780-6005			
Address: 1954							7)700 0000			
Lic. No.: TGC		Expires:08/								
Type: PLUM	IB Name:	MIHAI M. M	AN		Ph	one: (77	3)406-2820 x			
Address:3850										
Lic. No.: A201	997	Expires:01/	/13/2017							

Contractor Information										
Type: REFRIG Name: MIKE B CONSTRUC	CTION		Phone: (773	3)742-5411 x						
Address: 4107 OAKTON ST. FLOOR 1ST SKOKIE I	L 60076-									
Lic. No.: 219971-1 Expires:										
Lic. No.: 219971-1 Expires:										
Type: MASON Name: DURAAN CONCRE	TE,INC		Phone: (630))417-7743 X						
Address: 733 W. PLYMOUTH STREET VILLA PARK	K IL 60181									
Lic. No.: MC6557 Expires: 11/14/2016	i									
Type: PLUMB Name: MIHAI M. MAN			Phone: (773	3)406-2820 x						
Address: 3850 MAIN SKOKIE IL 60076-										
Lic. No.: BC058196863 Expires:07/01/2017										
Lic. No.: A201903 Expires:05/29/2017	7									
Type: VENT Name: MIKE B CONSTRUC	CTION		Phone: (773	B)742-5411 x						
Address: 4107 OAKTON ST. FLOOR 1ST SKOKIE I	L 60076-									
Lic. No.: 219971 Expires:										
Type: ELECT Name: D.C.L. ELECTRIC			Phone: (773	3)764-9608 x						
Address:6613 N. MAPLEWOOD AVE. CHICAGO II	L 60645-		-							
Lic. No.: SE5451 Expires:01/31/2017	,									
Fee Description	Amount	Waived	Status]						
DS RENO PERMIT FEE	\$419.90	N	PAID	J						
RENO PERMIT DEPOSIT FEE	\$300.00	Ν	PAID							
STOP WORK ORDER - PENALTY FEE	\$625.00	Ν	PAID							
ZONING FEE - RENOVATIONS	\$50.00	Ν	PAID							
	•	••								

\$1,394.90

Total Fees:

Page 2 of 2

203426 Case Entered Date: 03/20/2009 Case Status: Open



Case. No. Address: 1720 N. SEDGWICK ST Case. Type: DOB CIRCUIT COURT CASE **Description:**

		Case Data			
Disp. Code	Code Description	N	ext Date	Time	Room
DUMY	DUMMY COURT DATE	01	/01/2001	9:30 AM	1103
PRNT	DOCUMENT PRINT DATE				

				Ir	nspections				
Insp. #	Insp. Type	Partial	Waived	Assigned To	Started	Completed	Insp. By	Status	Mod. By
2670378	CN_COMP	LN	Ν		01/27/2009	01/27/2009	BL01037	FAILED	BL07004
from def	ects which m	nay adm	it rain. (tructure in sou 13-196-530, 1 f sheathing rot	3-196-530(e), 13-196-64	i)Southwe		
which ma	ay admit rain	. (13-1	96-530, ⁻	aves in good 13-196-530(c) d throughout.					
(13-196-				utters in good 641, 18-29-11				vest	
breaks, l	oose or rottin	ng boar	ds or tim	terior walls of bers and any 30(b), 13-196-	other condit	ions which m	ight admit r		
				ws in sound c vindow frames		l good repair.			
				w sash in goo)North rotted v			reasonably		

CN138056 - Remove accumulation of refuse and debris and keep premises clean. (13-196-580, 13-196-630)Rear at 2nd floor back and at grade junk, wood debris, plywood.

CN077014 - Failed to maintain fence in good condition and repair. (7-28-060, 13-196-630, 13-196-641)Front rotted 6' wood fence.

CN070034 - Failed to rebuild or replace dilapidated and dangerous porch. (13-196-570, 13-196-641)Rear 2 story, wood porch is dangerous and hazardous. It has rotted decking, missing handrails, missing pickets, handrails under 42", rotted stair stringers, rotted stair treads, missing stair risers, over notched columns, columns to beams missing bolts, open fire cuts, 6x6 beams at 8' span, lower handy man deck falling and collapsing. Plans and permits required for rear porch replacement.



Case. No.201748Case Entered Date: 03/11/2009Address:1720 N. SEDGWICK STCase. Type:CONSERVATION COMPLAINT INVST(Description:311 complaint SR# 802415869

Case Status: Open

				Insp	pections			
Insp. #	Insp. Type	Partial	Waived	Started	Completed	Insp. By	Status	Modified By
2670378	CN_COMP	L N	Ν	01/27/2009	01/27/2009	BL01037	FAILED	BL07004
from def	ects which m	ay admit	rain. (13-	196-530, 13-	l condition and 196-530(e), 13 d and buckled	8-196-641) So		OPEN
which m		. (13-196	6-530, 13- ⁻	196-530(c), a	air and free frond nd 13-196-641			OPEN
(13-196-		630(b), 1	3-196-641		pair and worki , 18-29-1105,			OPEN
breaks, l	oose or rottin	ig boards	or timber	s and any oth	building or struter conditions v 1) North and S	which might ad	dmit rain	OPEN
	35 - Failed to 550(b) and (f				dition and goo	d repair.		OPEN
					condition and s ndow sashes.	so it fits reasor	nably	OPEN
					ris and keep p at grade junk,			OPEN
	14 - Failed to 641) Front rot			good conditio	n and repair.	(7-28-060, 13-	196-630,	OPEN
13-196-6 missing treads, r	641) Rear 2 s handrails, mis nissing stair r	tory, woo ssing picl isers, ove	d porch is kets, hand er notched	dangerous a rails under 42 columns, co	nd dangerous and hazardous 2", rotted stair lumns to bean k falling and co	It has rotted of stringers, rotted of stringers, rotted of stringers, rotted of string bol	decking, ed stair Its, open	OPEN

permits required for rear porch replacement.

Administrative Holds for 1720 - 1720 N SEDGWICK ST

Rec. #	-	Address	Hold Description	Expired						
10739	1610	1758 N SEDGWICK ST	LANDMARK, OLD TOWN TRIANGLE DIST.							
113995	1720	1720 N SEDGWICK ST	STOPORDER #108093 ISSUED ON 08/14/2015							
114800	1720	1720 N SEDGWICK ST	ADMIN							
68648	1720	1720 N SEDGWICK ST	LANDMARKS: COLOR CODE OR							

CSR Complaints for 1720 - 1720 N SEDGWICK ST			
Call No. Type Address	Called Priority	Area Res. Date	Resolution Code
156486984BBA1720 N SEDGWICK ST12/01/15 STRDCN_C, 0701/15/16ACTIVE CASEGUTTERS ARE DILAPIDATED AND OVERFLOWING CAUSING WATERFALLS OF WATER ONTO NEIGHBORING PROPERTIES, WHEN IT SNOWED THERE WAS SEVERAL INCHES OF ICE - WATER DAMAGE FROM BAD GUTTERS - NEIGHBOR - WATER DAMAGE FROM BAD GUTTERS POURING WATER ONTO PROPERTY			
802415869 BBA 1720 N SEDGWICK ST DILAPIDATED	12/05/08 STRD CN	J_C,07 01/27/09 F	PROCESSED FOR COURT